

Annexure D

BUILDING SAFETY CERTIFICATE

No. 764

Dated: 06-09-2025

It is certified that the existing building **Sri.Shubhodaya Public School** (name of the building or premises) at **Parapur Taluka : Maski Dist:Raichur.** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor					

The building is owned/occupied by **Sri.Shubhodaya Public School**..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant Executive Engineer Public Works Department** (Name of Department/ Govt.) on 06-09-2025 (date of inspection) in the presence of **Secretary** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 06-09-2025 for a period 1 Yeas in accordance with rule and subject to compliance of the specific conditions as appended.

1. In Future If the building has any issues relating to any cracks, collapse and leakage of water immediate action should taken and you only the responsible
2. Should procure Fire Safety Certificate from Fire Department their recommendations should be followed and updated regularly
3. Original Documents of Building Should kept Safely
- 4.

Issued on 06-09-2025 at Lingasugur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name :

Designation :

Name & Address of Department/ Office: _____